

Date: 25th January 2023



TECH TOOL RELEASE NOTES

Version 2.8.175



Volvo Group

© Copyright AB Volvo 2023, inc. All rights reserved. Volvo is a registered trademark of Volvogroup.com, inc., as are other names and marks. Other marks appearing herein may be trademarks of their respective owners



Contents

TECH TOOL RELEASE NOTES 2.8.175	2
Overview	2
Limitations / Challenges	2
Recommended actions	2
Fixed Issues	3
Operation changes in the release	3
Diagnostic changes in the release	4
Known Issues and Workarounds	5



TECH TOOL RELEASE NOTES 2.8.175

Overview

These release notes give you an overview of new features and changes in Tech Tool. Please take your time to read through this news carefully as it will support in having the full benefit of the features in Tech Tool.

Tech Tool release 2.8.175 is available for download in the Client Update from week 04, 2023.

Limitations / Challenges

1. The system changes are limited with improvements to stability and performance of Tech Tool.
2. **Installation of Tech Tool version 2.8.150 and above will fail if Cisco Secure & Trend Micro Endpoint software is installed on the computer. Recommend staying with the currently installed version of Tech Tool.**
 - a. If the user is installing Tech Tool via ISO/Web, installation will fail.
 - b. If the user is updating Tech Tool via client update, installation will get corrupted. If installation gets corrupted, it is recommended to contact Tech Tool support team.
3. Restarting Tech Tool daily is recommended to free up resources and improve the application's performance.
4. It is recommended to perform 'Finish work' at the end of a connected product's session before connecting to the next product. This will speed up the process of connecting to the next product.

Recommended actions

1. Before initiating Tech Tool installation via Client update, ensure that all the Windows updates have completed. Otherwise, Windows Update might cause the computer to restart, which may lead to the reinstallation of Tech Tool.
2. Restart the computer after installing Tech Tool for both a fresh installation and an update via Client Update.



Fixed Issues

Description	Brands
Automatic version identification support is extended for VM models with VERSION2 & VERSION3 vehicles.	VTC

Operation changes in the release

Operation	Changes	Brands	Models
33445-3 'Ignition Switch, Test'	Operation support has been added for MDE8 VM2023.	VTC ✓	VM
59377-3 'Reinitiate Learned Parameters, Calibration'	Operation support has been added for MDE8 VM2023.	VTC ✓	VM
59361-3 'Sensor Yaw Rate, Calibration'	Operation support has been added for MDE8 VM2023.	VTC ✓	VM
38118-3 'Gauge Checks, Instrument Cluster'	Operation support has been added for MDE8 VM2023.	VTC ✓	VM
3241-05-03-02/32425-3 'Program Motor Control Unit (MCU)'	Operation support has been added for Battery Electric Vehicles.	VTC ✓ MACK ✓	VNRe LRBe



Diagnostic changes in the release

Diagnostic	Changes	Brands	Models
Diagnostic Update	Fault tracing instructions are updated to support the cooling circuit three-way valve for Electric Vehicle Control Module (EVCM).	VTC ✓	VNRe
Diagnostic Update	Fault tracing instructions are updated to support the inlet actuator for Combined Charging system Control Module (CCCM).	VTC ✓ MACK ✓	VNRe LRBe



Known Issues and Workarounds


Issue no:	Issue Description	Brands
1.	Tech Tool Services [BAF service] are not getting started.	ALL
2.	Code integrity check failed pop-up might be observed during the installation.	ALL
3.	While switching between the tabs, Tech Tool might freeze, or an error pop-up is displayed.	ALL
4.	Impact tab not loading in Windows 11 computer.	ALL
5.	Tech Tool installation progress bar freeze during Client update.	ALL
6.	Application error pop-up in Tech Tool.	ALL

Issue-1: Tech Tool Services [Baf service] are not getting started.

Cause: When the computer is closed and enters Sleep or Hibernate mode, Tech Tool might get into the “Services not started” error.

Suggestion:

1. We recommend changing the windows settings so that the computer does not go into Sleep or Hibernate mode. (Drawback: power consumption). Please follow the instructions stated in '[Power Settings Modification.doc](#)'.
2. If the issue occurs, restart the computer, then launch Tech Tool.
3. If not recovered, follow the below steps after restarting the computer.
 - a. Search for Task Manager in search field from task bar.
 - b. Right-click on the Task Manager.
 - c. Select “Run as administrator”. (Contact local IT team if you don't have administrator privilege)




The screenshot shows the Windows Task Manager Performance tab. The top navigation bar includes 'File', 'Options', and 'View'. Below the navigation bar are tabs for 'Processes', 'Performance', 'App history', 'Startup', 'Users', 'Details', and 'Services'. The 'Performance' tab is active, displaying a table of system resource usage. The table has columns for 'Name', 'Status', 'CPU', 'Memory', 'Disk', and 'Network'. The 'CPU' column shows 42% usage, 'Memory' shows 86%, 'Disk' shows 11%, and 'Network' shows 0%. The 'Name' column lists various applications, including Windows Explorer (4), Task Manager, Snagit Editor, Snagit (3), Notepad++ : a free (GNU) sourc..., Microsoft Word (32 bit) (2), Microsoft Teams (10), Microsoft Outlook (32 bit) (7), Google Chrome (18), and Blend for Visual Studio (32 bit) (4). The 'Status' column shows the status of each application. The 'CPU', 'Memory', 'Disk', and 'Network' columns show the percentage of usage for each resource. The 'Task Manager' row is highlighted in blue. Below the table, there is a section for 'Background processes (141)' with a search icon and a list of background processes, including 'Your Phone (2)' and 'WMI Provider Host'. At the bottom of the window, there are buttons for 'Fewer details' and 'End task'.

Name	Status	42% CPU	86% Memory	11% Disk	0% Network
> Windows Explorer (4)		10.3%	83.7 MB	0.2 MB/s	0 Mbps
> Task Manager		1.3%	29.5 MB	0.1 MB/s	0 Mbps
> Snagit Editor		0%	46.7 MB	0.1 MB/s	0 Mbps
> Snagit (3)		0%	11.1 MB	0 MB/s	0 Mbps
> Notepad++ : a free (GNU) sourc...		0%	1.3 MB	0 MB/s	0 Mbps
> Microsoft Word (32 bit) (2)		1.2%	195.5 MB	0.1 MB/s	0 Mbps
> Microsoft Teams (10)		0.2%	1,004.6 MB	0.1 MB/s	0 Mbps
> Microsoft Outlook (32 bit) (7)		8.9%	210.9 MB	0.1 MB/s	0 Mbps
> Google Chrome (18)		2.0%	490.1 MB	0 MB/s	0 Mbps
> Blend for Visual Studio (32 bit) (4)		0%	66.7 MB	0 MB/s	0 Mbps
Background processes (141)					
> Your Phone (2)		0%	0.9 MB	0 MB/s	0 Mbps
WMI Provider Host		0%	0.8 MB	0 MB/s	0 Mbps




- d. Click on the Services tab and search for the “VolvoTechToolServiceController” service. Right-click on the service and select Start.



Issue-2: Code integrity check failed pop-up might be observed during the installation. Recommend staying with the currently installed version of Tech Tool.

Cause: If the user has **Cisco Secure & Trend Micro** Endpoint software installed on the computer, Tech Tool installation will fail.



Suggestion:


1. If the user installs Tech Tool via ISO/Web, Tech Tool installation will fail.
2. If the user updates Tech Tool via Client Update, the installation will get corrupted. If installation gets corrupted, kindly contact Tech Tool support team.

Note: We recommend to disable Client Update Service to avoid automatic Tech Tool update. Information on how to disable Client Update Service is provided in the [Video](#).



Issue-3: While switching between the tabs, Tech Tool might freeze.

Cause: Under investigation.




Suggestion: Kindly follow the below steps:

1. Ensure that there is a stable network as shown in the icon
2. Restart Tech Tool.
3. If not able to recover, restart the computer.



Issue-4: Impact tab not loading in Windows 11 computer.

Cause: Under investigation.




Suggestion: Open Impact tab outside Tech Tool in web browser.



Issue-5: Tech Tool installation progress bar freeze during Client Update.


Cause: Under investigation.



Suggestion: Restart computer if the progress bar freezes for more than 30 minutes.

Issue-6: Application error pop-up in Tech Tool.

Cause: Under Investigation.



Suggestion: Restart Tech Tool.

Note: For any issues & Support, kindly use your normal channels.